





Assembly instruction


300 without gas lift




two people




remove the transport protection




1.1




1.2





2.1




2.2




2.3




3.1




3.2




3.3




3.4




4.1




4.2




4.3




4.4




4.5




5.1




5.2



5.3







5.4




5.5

check back is fixed










Exchange click plastic



bag with new click plastic



new click plastic



silent click