







OTARI - Montagehandleiding





1 x SW4 hex




18 x Ø4x20


9 x M6x30

9 x

1. 3 x Iron legs
same dimension




6 x Ø4x20




2.


1 x



3 x M6x30






3.




4.

3 x



5.



Max 5kg

