





Assembly instruction


300 with gas lift




two people




remove the transport protection




1.1




1.2




1.3




1.4



1.5




2.1




2.2




2.3




2.4





3.1




3.2




3.3




4.1




4.2




4.3




4.4




5.1




5.2




5.3



5.4




5.5




5.6


6.1




6.2



6.3








6.4




6.5


check back is fixed












Exchange click plastic



bag with new click plastic



new click plastic



silent click